S2995

List of reference symbols

- 1 substrate
- 2 trench
- 3 mask
- 5 selective oxide
- 6 HDP oxide
- 7 void